
PREVENTION OFFICERS ASSOCIATION

ACCEPTABLE FIRE SPRINKLER / DOMESTIC HOOK--UPS



- 1. AN INDICATING-TYPE VALVE SHALL BE INSTALLED IN A LOCATION WHERE IT SHUTS OFF BOTH THE FIRE SPRINKLER AND THE DOMESTIC SYSTEMS.
- 2. INDICATING VALVE SHALL BE INSTALLED ABOVE FINISHED GRADE.
- 3. BALL-TYPE VALVE IS ACCEPTABLE; GATE VALVES ARE NOT ALLOWED.
- 4. SEPARATE VALVE FOR THE FIRE SPRINKLER SYSTEM IS NOT ALLOWED.
- 5. UNDERGROUND PIPING TO BE FLUSHED PRIOR TO RISER CONNECTION.
- 6. FIRE SPRINKLER ALARM TO BE WIRED TO REFRIGERATOR CIRCUIT.
- 7. A SEPARATE VALVE SHALL BE INSTALLED FOR DOMESTIC SYSTEM ONLY SO THE FIRE SPRINKLER SYSTEM CAN REMAIN IN OPERATION DURING DOMESTIC SYSTEM REPAIRS.

Monterey County Fire Prevention Officers Association Form # 6

revised August 30, 1996